

Safety Soapbox Absolute Shocker

17 September 2014



Victorian WorkCover
Authority



A genius IQ is not needed to know this site and *system of work* is unsafe.

A few low-lights are:

- Sub-standard benching of the excavation (risk of wall collapse)
- Working under a truck on the excavation edge, the discharge chute and another worker
- Truck too close to edge of excavation
- Lack of fall protection for the truck operator
- Lack of fall protection to stop people falling into the excavation

For more information, see the Code of Practice – Safety precautions in trenching operations at vwa.vic.gov.au

Absolute Shocker is published by the Victorian WorkCover Authority to promote safer work practices; it may be freely copied for such purposes.